



<b>Project Name:</b> South Gate Fireworks ER		<b>Site Location:</b> 3570 Fruitland Avenue, Maywood, CA	<b>TDD No.:</b> 0002/1302-T2-R9-14-07-0003
<b>Photo No. 1</b>	<b>Date:</b> 6/27/2016		
<b>Direction Photo Taken:</b>  South			
<b>Description:</b>  Fire-damaged structure.			


<b>Photo No. 2</b>	<b>Date:</b> 6/27/2016	
<b>Direction Photo Taken:</b>  South		
<b>Description:</b>  Totes containing metal scrap and electronic debris.		


<b>Project Name:</b> South Gate Fireworks ER		<b>Site Location:</b> 3570 Fruitland Avenue, Maywood, CA	<b>TDD No.:</b> 0002/1302-T2-R9-14-07-0003
<b>Photo No. 3</b>	<b>Date:</b> 6/27/2016		
<b>Direction Photo Taken:</b>  South			
<b>Description:</b>  Fire-damaged wood debris.			

<b>Photo No. 4</b>	<b>Date:</b> 6/17/2016	
<b>Direction Photo Taken:</b>  South		

**Description:**

Metal scrap and drums  
on the west side of the  
property.

<b>Project Name:</b> South Gate Fireworks ER		<b>Site Location:</b> 3570 Fruitland Avenue, Maywood, CA	<b>TDD No.:</b> 0002/1302-T2-R9-14-07-0003
<b>Photo No. 5</b>	<b>Date:</b> 6/17/2016		
<b>Direction Photo Taken:</b>  South			
<b>Description:</b>  Drums and metal scrap containers under the fire-damaged roof.			

<b>Photo No. 6</b>	<b>Date:</b> 6/20/2016	
<b>Direction Photo Taken:</b>  South		
<b>Description:</b>  Drums and metal scrap containers under the fire-damaged roof.		

